

1.5T CTL PHASED ARRAY COIL (T3014CF) TROUBLESHOOTING GUIDE

Section I: Checking the PIN diodes with Digital Multimeter (DMM)

NOTE:


The diodes in this coil are NOT FIELD REPLACEABLE. The steps in this section are included to provide a means of remote troubleshooting to determine if the coil is defective without using system time as well as providing root cause failure to the repair source.

- 1) Select the DIODE TEST function on the Digital Multimeter(DMM)
- 2) Connect the NEGATIVE lead of the DMM to the external cable connector row A. Connect the POSITIVE lead to the external cable connector row B. Refer to Table 1 and Diagram 1.
- 3) A reading of 0.400 to 0.900 should be observed on the DMM
- 4) If a reading below 0.400 is observed in either direction, either the output cable is shorted or a PIN diode is bad.
- 5) If a reading above 0.900 is observed in step 2, both PIN diodes are defective. **REPLACE THE COIL.**
- 6) Connect the NEGATIVE lead of the DMM to the external cable connector row B. Connect the POSITIVE lead to the external cable connector row A. Refer to Table 1 and Diagram 1.
- 7) A reading of INFINITY should be observed on the DMM.
- 8) If a reading of INFINITY is observed in both directions, either the output cable is open of both PIN diodes are open.
- 9) If any of the above conditions fails, **REPLACE THE COIL.** The PIN diodes are not FRU'S.

**TABLE 1
DIODE TEST CONNECTIONS**

COIL NUMBER	POSITIVE LEAD CONNECTION		NEGATIVE LEAD CONNECTION	
	FOR STEP 2	FOR STEP 4	FOR STEP 2	FOR STEP 4
1	B3	A3	A3	B3
2	B5	A5	A5	B5
3	B7	A7	A7	B7
4	B9	A9	A9	B9
5	B11	A11	A11	B11
6	B13	A13	A13	B13

**PIN LOCATIONS ON EXTERNAL CONNECTOR
DIAGRAM 1**



Section II:

Checking the External Cable

- 1) Select the DIODE TEST function on the Digital Multimeter (DMM).
- 2) Connect the Negative lead of the DMM to the external cable connector row A. Connect the POSITIVE lead to the external cable connector row B. Refer to Table 3-7 and Diagram 1.
- 3) Flex the external cable, especially near the connectors and the strain relief, and observe that a reading of 0.400 to 0.900 should remain on the DMM, with no instabilities or fluctuations.
- 4) Connect the NEGATIVE lead of the DMM to the external cable connector row B. Connect the POSITIVE lead to the external cable connector row A. Refer to Table 1 and Diagram 1.
- 5) Flex the external cable, especially near the connectors and the strain relief, and observe that a reading of INFINITY should remain on the DMM, with no instabilities or fluctuations.
- 6) If the cable fails any of the above tests, **REPLACE THE CABLE (2133085)**.

TROUBLESHOOTING STEPS IN REVIEW:

- 1) **CHECK THE DIODES.**
- 2) **CHECK THE CABLE.**
- 3) **IF THE DIODES ARE BAD, REPLACE THE COIL (T3014CF).**
- 4) **IF THE CABLE IS BAD, REPLACE THE CABLE (2133085).**