

9 Inch GP Coil Replacement

EFFECTIVITY

All Signa Ovation Systems with 9 Inch GP Coil, model number 2269510 with the following serial numbers:
805306YM8 (Nara), 801170YM2(Service Parts)

All Signa Ovation Systems with 9 Inch GP Coil, model number 2269512 with the following serial numbers:
805305YM0(Service Parts)

PURPOSE

Low SNR Image problem might occur by using current 9 Inch GP Coil (2269510: For Japan, 2269512: For Outside Japan) because of the cable routing.

New 9 Inch GP Coil(2269510-2: For Japan, 2269512-2: For Outside Japan) solves this problem.

MATERIALS

Order the following parts if your site 9 Inch GP Coil serial number is listed in the effectivity.

Japanese Site

ITEM	PART NUMBER	DESCRIPTION	Qty.
1.	2269510-2	9 Inch GP Coil	1

Outside Japan

ITEM	PART NUMBER	DESCRIPTION	Qty.
1.	2269512-2	9 Inch GP Coil	1

SPECIAL TOOLS AND TEST EQUIPMENT:

Signa Ovation CD-ROM Service Document (2283085)

Procedure:

1. Replace the 9 Inch GP Coil.
2. Measure the SNR of 9 Inch GP Coil.
Refer to CD-ROM. (Installation/10th ~ 11th day/Surface Coil Tuning and SNR Check/9 Inch Coil SNR).
3. Return the old 9 Inch GP Coil to the parts center. This coil will be modified and stocked in the parts center.