

**RF Cable Core Installation****Effectivity:**

Signa Ovation Shipped after FW28 2002.

**Note**

The procedure in this service note needs to be performed during the System Installation.  
This service note notifies that RF cable care installation is added in Installation Procedure.  
This information will be added in the next Signa Ovation SV Document CD-ROM.

**Overview:**

Since the following two RF cables and cores are shipped separately after FW28 2002, it is necessary to install cores to the RF cables at site.

**RF Cables**

| <b>Item</b> | <b>Part Number</b> | <b>Part Name</b>   | <b>Qty</b> |
|-------------|--------------------|--------------------|------------|
| 1           | 2263076            | RF Cable (RUN#887) | 1          |
| 2           | 2263076-2          | RF Cable (RUN#888) | 1          |

**Note**

The cables above are included in HFO RF Cables and Adapter (2263647).  
Parent of 2263647 is Elec Collector(2285451).

**Core and Cramp**

| <b>Item</b> | <b>Part Number</b> | <b>Part Name</b> | <b>Qty</b> |
|-------------|--------------------|------------------|------------|
| 1           | 2298512            | Core             | 4          |
| 2           | U0201AC            | Cramp            | 4          |
| 3           | U0204AC            | Cramp            | 4          |

**Note**

The parts above are included in 0.35 Site Collector (2282879).

# SERVICE NOTES

Jul 8th, 2002

Page 2 of 2


FILE TITLE

Signa Ovation System

SN62706


## Procedure:

1. Install two core around the RF Cable (Penetration Panel Connection side).
2. Fix each core with cramp(U0201AC).



**CORE INSTALLATION 1**  
Illustration 1

3. Fix two cores with one cramp(U0204AC) as following illustration.



**CORE INSTALLATION 2**  
Illustration 2

4. Perform the same procedure to the another cable also.

Yutaka Masumo  
**GEYMS TP Gr. -MR**